			Sch	edule 1: Approach to						
	School No:	2475		School Name:	Hunslet Moor Primary So	chool				
External a	rea: approach from publ	ic transpor	t to schoo	ol entrance gates		_			_	
Room No Identified on	Question	Provision	n Made?	Comments/Site Notes	Recommendations	Quantity	Priority	Cost	Respo	nsibility
CAD Drawing		Y/N	Partial (%)				A,B,C,D		LEA	School
	Is the route to the school entrance from the nearest point of public transport, well signed, well lit, free of broken slabs, etc.?	Y		All signage now in place						
	Are there separate entrances for cars and pedestrians?	Υ		N/A						
	Is the route wide enough, and free of kerbs?	Y		3 x disabled parking spots added in top car park						

	School No:	2475		School Name:	Hunslet Moor Primary So	hool				
	External area:		•		•					
Room No Identified on CAD	Question	Provision Made?		Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	Respo	nsibility
Drawing		Y/N	Partial (%)				7,5,5,5		LEA	School
	Are accessible car parking bays signposted from the car park entrance?	Y		All bays marked and with symbols						
	Are these bays wide enough and long enough to allow transfer onto a wheelchair?	Y								
	Are the bays smooth, (free from loose stones), well lit, and signposted as being identified for disabled people only?	у								

			Scried	ule 3: External Ram						
_ , .	School No:	2475		School Name:	Hunslet Moor Primary Scl	nool				
	rea: school grounds				T			1		
Room No Identified on		Provision	n Made?				Duianita		Respo	nsibility
CAD Drawing	Question	Y/N	Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	LEA	School
	Is the ramp properly graded, wide enough, slip resistant, with suitable handrails both sides?	Y		Ramp on KS2 playground is now accessible as building works complete						
	If no permanent ramp is provided, can a portable ramp be made available?	N		Ramp on KS2 playground wide enough but bushes need maintaining - this is now complete and monitored through year	Ramp on KS2 playground to be maintained. Tools have been bought for site team to do this. SLA with LCC from 01.04.21 to maintain grounds.					
	Are there suitable steps (as an alternative to the ramp), with easily identifiable step nosings, handrails both sides, and are well lit?	90%		Steps on to upper KS2 playground accessible with handrails	VH to link with site team to mark up nosing now playground is complete. Nosings painted May 2021.					


	Schedule 4: Main Entrance, lobby and Reception Areas										
	School No:	2475		School Name:	Hunslet Moor Primary Scl	hool					
	Location:										
Room No Identified on CAD Drawing	Question	Provision Y/N	Made? Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	Respondent LEA	nsibility School	
	Is the main entrance clearly signposted, well lit, and distinguishable from facade?	Y									
	Can people on each side of the door, either seated or standing, see each other?	Y									
	If fitted, are door control systems fitted at heights suitable for all users?	Y									
	Is the door handle easy to use, of the correct type, at the right height, and tonally contrasted from the door?	Y									
	Does the door pressure allow ease of access for all users?	Y		door and gate can be opened with ease but would prove difficult for a wheel chair user	Add procedure to policy which states that office would support with access in event of a disabled user entering from main entrance						

	thresholds flush and level, mat wells firmly fixed?	Υ					
users adeq	ne door wide enough for all rs (800mm clear), with quate space for wheelchair r to open door?	Υ					
whee of the	ted , does the lobby allow elchair users to move clear ne outer door before ning the inner door?	Υ					
signa Rece visua with I	ppropriate information lage provided at the leption, for people with al impairments or others lower sight levels eelchair users)?	N		Val to link with council H&S team for recommendations			
had a	e front line staff (reception) access awareness/ ality training?	N		Val to link with Sarah Newton to book equality training for KW, SN, VH, FS booked by Dec 2020			

	_	Schedule	5: Corrid	ors, horizontal move	ment and activity sp	aces				
	School No:	2475		School Name:	Hunslet Moor Primary Sc	hool				
	Location:									
Room No Identified on CAD Drawing	Question	Provision Y/N	Made? Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	Respoi	nsibility School
	Are corridors a minimum width of 1200mm? (Better to be 1800mm for wheelchairs to pass each other)	Y								
	Do any windows (natural light), or artificial light provide glare or silhouettes?	Υ								
	Do "communication/activity spaces" have good acoustics, and the provision of an induction loop?	Y								
	Are suitable signs provided, from both standing and seated positions, where necessary?	Y								
	Are fire extinguishers (or hose reels) positioned to ensure they do not create hazards for visually impaired people?	Y		On moveable stands placed in locations by Fire Solve based on most recent recommendations						

				Schedule 6 - Doo						
	School No:			School Name:	Hunslet Moor Primary So	chool				
Danie Na	Location:		M d-O					1	D	
Room No Identified on		Provisio	n Made?				Priority		Respo	nsibility
CAD Drawing	Question	Y/N	Partial (%)	Comments/Site Notes	Recommendations	Quantity	A,B,C,D	Cost	LEA	School
	Is the door/s necessary, can it/they be removed?	n/a	n/a							
	Can fire doors be held open on magnetic devices (corridors)?	Y								
	Are doors well contrasted from their surroundings?	Y								
	Is the door handle easy to use, of the correct type, at the right height, and tonally contrasted from the door?	Y								
	Can people on each side of the door, either seated or standing, see each other?	Y								
	Is the door wide enough for all users (800mm clear), with adequate space for wheelchair user to open door?	Y								

If double doors, does one leaf allow 800mm clear opening width?	Y		Unsuitable doors have now all been removed and replaced 11/18
-----------------------------------------------------------------	---	--	---------------------------------------------------------------------



			- vertical	movement, internal						
	School No:	2475		School Name:	Hunslet Moor Primary So	hool				
	Location:									
Room No Identified on CAD Drawing	Question	Provision Y/N	Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	LEA	nsibility School
	If provided, Is the ramp properly graded, wide enough, with suitable handrails both sides?	N		No permanent ramps in school as not required						
	Are surfaces slip resistant, with kerbs at the edges?	N								
	If no permanent ramp is provided, can a portable ramp be made available?	Y		Ramps held in Ks2 upper corridor in event of fire. Lift to be used in non emergency						
	Are there steps as an alternative to the ramp, with suitable treads and rises, with easily identifiable step nosing?	Y		Ramps held in Ks2 upper corridor in event of fire. Lift to be used in non emergency						
	Are the steps maintained, well lit, with suitable handrails both sides, and tactile warnings at the top and bottom?	Y								

			Sched	lule 8 - Vertical move	ement, stairs					
	School No:	2475		School Name:	Hunslet Moor Primary Scl	hool				
	Location:					ı	ı			
Room No Identified on CAD Drawing	Question	Provision Y/N	Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	LEA	nsibility School
	Are the stair risers and steps the same height and length (open risers not recommended) and are the step nosings easily identifiable?	Y								
	Are there suitable continuous handrails to both sides, with tonal contrast from background?	Y								
	Are there suitable landings provided at intermediate levels on stairs?	Y								
	Is suitable visual and tactile information fitted at each floor level?	N		Signage of level and information not accessible on floor levels	VH to contact H and S team re tactile signage					
	Is there suitable lighting?	у								

			al moveme	ent, Passenger Lifts,			airlifts			
	School No:	2475		School Name:	Hunslet Moor Primary So	hool				
	Location:					1		1		
Room No Identified on CAD Drawing	Question	Provisio Y/N	Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	LEA	School
	Is a passenger lift provided within the school?	у								
	Is there unobstructed space (1500mm x 1500mm) in front of the doors, and do the doors have a clear opening width of 800mm?	Y								
	Are the internal dimensions of the lift cabin 1100 x 1400mm (preferred 1100 x 2000mm)min, and is the lift fitted with suitable support rails on three sides??	Y								
	Are the controls on the landing and in the lift cabin, including emergency phone, within easy reach and clearly visible for all users (within zone of 900mm and 1200mm from floor)?	Y								

Are these controls clearly visible in contrasting colours and with raise (tactile) characters/numbers?	Y				
Does the lift have audible announcements and visual displays?	Y				
Is a platform lift or platform stairlift provided within the school? Note - platform stairlifts are not advisable.	N				
Are controls clearly identifiable and within reach of all users?	Y				
Does the stairlift platform when not in use automatically revert to folded position?	N/A				

			Sched	lule 10 - WC Provision						
	School No:	2475		School Name:	Hunslet Moor Primary So	hool				
	Location:									
Room No Identified on CAD Drawing	Question	Provisio Y/N	n Made? Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	Respo LEA	nsibility School
	Is there WC provision for ambulant people with disabilities? (eg. Grab rail fitted to one WC cubicle) and is travel distance no greater than for an able bodied person?	Y								
	Is the lobby large enough to allow easy access, and is the WC door easy to operate?	Y								
	Are the floors slip resistant?	Y								
	Are fittings easily distinguished from their background?	Y								
	Are compartment doors controls easily gripped and operated?	Y								
	Can ambulant disabled people manoeuvre and rise and lower themselves in a standard cubicle?	Y								

		0.475	Julieu	ule 11 - Accessible V						
	School No:	2475		School Name:	Hunslet Moor Primary Sch	nool				
Room No	Location:	Provisio	n Made?						Respo	onsibility
Identified on CAD Drawing	Question	Y/N	Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	LEA	School
	Is there an accessible WC, with its location clearly signed, and is the travel distance no greater than for an able bodied person?		80%	currently a pupil working in Year 1/ Year 2 would have to travel a long distance to access the toilet	Review refit of existing toilets in new area of building for consideration in further development					Disabled suite constructed summer 2021
	Are there suitable fittings, which are easily distinguished from their background, and are they fitted in suitable positions?	Y								
	Does the door have a clear opening of 900mm, and are doors controls, light switch and locks easily reached and operated?	Y								
	Are floor finishes slip resistant?	Υ								
	Are management procedures in position to maintain viability of facility?	Y								
	Does the door have the capacity to open outward to ensure that entry can be gained in the event of someone falling and blocking the doorway?	Y								

	1		Schedu	le 12 - Changing/Sh	ower Facilities					
	School No:	2475		School Name:	Hunslet Moor Primary Sc	hool				
	Location:									
Room No		Provisio	n Made?						Respo	nsibility
Identified on CAD Drawing	Question	Y/N	Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	LEA	School
	Are there changing facilities?	Y		In kitchen for staff						
	Is a shower compartment provided which is suitable for use by people with disabilities?	N		No current shower or washing facilities on site for staff or pupils	Recommendations sought no changing facillities required at a primary school					
	Is the height of the shower head variable?	N								
	Have a tip-up seat and suitable handrails been provided?	N								
	Is there a dressing cubicle and does it comply with required size and layout?	N								
	Are lockers easily reached and operated?	Y								
	Are all fittings readily distinguishable from their background?	N/a								
	Does the floor have a slip resistant finish?	N/a								

			_	Schedule 13 - Bathr	ooms					
	School No:			School Name:	Hunslet Moor Primary So	chool				
Room No	Location:		n Made?			T			Resno	nsibility
Identified on CAD Drawing	Question	Y/N	Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	LEA	School
	Is there a bathroom?	N								
	Is the bathroom provided with fittings suitable for use by people with disabilities inc assisted use?	N/a								
	Are all fittings easily reached and operated?	N/a								
	Are all fittings readily distinguishable from their background?	N/a								
	Does the floor have a slip resistant finish?	N/a								
	Is a hoist provided?	N/a								

## Schedule14: Fixtures and Fittings School No: 2475 School Name: Hunslet Moor Primary School Location: Room No **Provision Made?** Responsibility Identified on **Priority** Question **Comments/Site Notes** Recommendations Quantity Cost A,B,C,D CAD Partial (%) Y/N **LEA** School Drawing Are there reception counters, Υ services desks or serveries? Is provision made for Open window and induction wheelchair users (both sides) Υ loop available if required and are induction loops fitted? Is glare or silhouetting avoided at these counters (design and У positioning)? Is seating provided, that are stable, with arm rests, and is there sufficient space for a wheelchair user? Do tables allow for wheelchair access? If provided, are telephones phones in classrooms are too fixed at a height that allows high but would always be able easy access by wheelchair to access a phone at height in offices users? Are telephones equipped with induction couplers for hearing У aid users? VH Look into Is a text phone available? recommendations and n requirements on this

Is the lighting in the school controllable and adjustable to meet the needs of individual pupils and the task they are working on?	у				
If the school is fitted with fluorescent lighting only is it likely to cause inconvenience to people with hearing impairments (background noise and electronic signals)?	No	All new lighting fitted in line with recommendations 8/18			
Is the environment free of unnecessary noise e.g. heating units?	у				
Are induction loops fitted wherever information is given or meetings are being held?	у	portable induction loop held by school			
Are tea, coffee facilities and vending machines accessible and usable by all?	у	New staffroom now accessible would eed to use that for now			

			_	Schedule15: Kitche	ens					
	School No:	2475		School Name:	Hunslet Moor Primary So	chool				
Door No	Location:	Draviala	n Mada2	ı		1		ı	Daama	
Room No Identified on CAD Drawing	Question	Y/N	n Made? Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	LEA	nsibility Schoo
-	If provided, does the kitchen have fittings suitable for use by disabled people?	N		counters are too high for wheel chair user new fitting VH / SN contact catering for their equality accessibilty policy re kitchen						
	Is the kitchen of adequate size and layout for disabled people ?	N		new layout would make it difficult to navigate new fitting VH / SN contact catering for their equality accessibilty policy re kitchen						
	Are all fittings readily distinguishable from the background?	Y								
	Is lighting adequate?	Y								
	Does the floor have a slip resistant finish?	Y								

			S	chedule17: Means o						
	School No:	2475		School Name:	Hunslet Moor Primary Scl	nool				
	Location:									
Room No Identified on CAD Drawing	Question	Provisio Y/N	Partial (%)	Comments/Site Notes	Recommendations		Priority A,B,C,D	Cost	Respo LEA	nsibility School
	Is there an audible alarm system?	у								
	Is the audible fire alarm supplemented by a flashing light system?	у								
	Are ground floor exit routes as accessible as the main entrance routes?	у								
	Are Means of Escape strategies in position to ensure disabled people are evacuated safely?	у		3 individual PEEPs written for each individual who requires extra support	PEEPs and SEEPs need annually updating by SENDCO					
	If people with disabilities cannot completely evacuate the building can they reach places of safety or refuge, which are clearly signed and of the right size?	у								
	Are there Personal Emergency Egress Plans in place members of staff who may require assistance?	N/a		No current staff require PEEPS.						

			Sch	edule18: Building Ma	anagement					
	School No:	2475		School Name:	Hunslet Moor Primary Scl	hool				
Room No	Location:	Provisio	n Made?					Ī	Respo	nsibility
Identified on CAD Drawing	Question	Y/N	Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	LEA	School
	Are the external routes (including steps and ramps) kept clear, unobstructed and free from surface water, ice and snow?	Y		2019 Extra salt bins in situ around grounds.	Regularly inspection by site management staff in bad weather VH consider placement of main entrance salt bin					Y
	Are accessible car parking spaces only used by disabled drivers and are kept clear of obstructions?	Y								
	Is door ironmongery regularly maintained?	Υ			Any problems to be e mailed to SBM and/or put on site board by SBM office for Caretaker to pick up					Y
	Are lifts, platforms and stairlifts regularly serviced ?	Υ		New lift from Sept 2018 under 12 month warrenty .	Sept 2019 annual SLA with Thryssen Krups who installed the lift.					Y
	Are accessible WC's kept clear and not used for storage?	Y								Y
	Are appropriate cleaning materials used to ensure that the cleaning and polishing of slip resistant floors does not make them shiny / slippery?	Y			Follow guidelines					Y
	Do you consider tonal and colour contrast before a redecoration scheme?	Y								

Do new signs integrate effectively with current signage?	Y						Y
Are windows, blinds and lamps checked to ensure they are kept clean and in working order?	Y						
Are induction loops and infra red systems clearly signed and checked regularly?		80%	Induction loop found. Needs testing	Induction loop to be kept in main office. Sarah Newton asked to test. Needs checking.			Υ
Are fire alarm systems regularly maintained, and are fire exit routes regularly checked for obstacles?	Y						
Is there a fire escape strategy for visitors who may require assistance?	Y						
Is there a personal egress plan prepared for any member of staff who may require assistance?			N/A at present time				
When temporary facilities/displays are installed are disabled pupils/ visitors considered?	Y						

		5	Schedule	19: Curriculum						
	School No:	2745		School Name:	Hunslet Moor Primary Sch	nool				
	fES/o462/2002:Identifying			, Section 3- How doe	es your school delive	r the curi	riculum?			
Room No Identified on CAD Drawing	Queston	Provision Y/N	Partial (%)	Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D	Cost	Respo	onsibility
									LEA	School
	Do you ensure that teachers and teaching assistants have the necessary training to teach and support disabled pupils?	Y		Regular inclusion and SEND CPD and provision lots of professionals support EG DAHIT/ SENIT / Physiotherapy/ STARS		N/A	N/A	N/A		х
	Are your classrooms optimally organised for disabled pupils?	Υ		Supported by the recent expansition	Continue to monitor this based on the furniuture placement	N/A	N/A	N/A	х	
	Do lessons provide opportunities for all pupils to achieve?	Y				N/A	N/A	N/A		x
	Are lessons responsive to pupil diversity?	у		Carefully designed curriuclum based on cultural diversity		N/A	N/A	N/A		x
	Do lessons involve work to be done by individuals, pairs, groups and the whole class?	у				N/A	N/A	N/A		x
	Are all pupils encouraged to take part in music, drama and physical activities?	у		Inclusive planning in all subjects		N/A	N/A	N/A		х
	Do staff recognise and allow for the mental effort expended by some disabled pupils, for example using lip reading?	у				N/A	N/A	N/A		х
	Do staff recognise and allow for the additional time required by some disabled pupils to use equipment in practical work?	у				N/A	N/A	N/A		x

Do staff provide alternative ways of giving access to experience or understanding for disabled pupils who cannot engage in particular activities, for example some forms of exercise in physical education?	У		N/A	N/A	N/A	X
Do you provide access to computer technology appropriate for students with disabilities?	у	ongoing investment in ICT to support pupil use.	N/A	N/A	In model PP spend	Х
Are school visits, including overseas visits, made accessible to all pupils irrespective of attainment or impairment?	у		N/A	N/A	N/A	X
Are there high expectations of all pupils?	у		N/A	N/A	N/A	X
Do staff seek to remove all barriers to learning and participation?	у		N/A	N/A	N/A	X

	School No:		l	erials in other Forma School Name:	Hunslet Moor Primary So	hool				
source: D	fES/o462/2002:Identifying		o Access.				Is in othe	r forma	ts?	
Room No	Question	Provision		Comments/Site Notes	Recommendations	Quantity	Priority A,B,C,D			nsibility
CAD Drawing		Y/N	Partial (%)					Cost	LEA	School
	Do you provide information in simple language, symbols, large print, on audiotape or in Braille for pupils and prospective pupils who may have difficulty with standard forms of printed information?		80%	no braille information. Pupils met 1-1 to support with verbal information						
	Do you ensure that information is presented to groups in a way which is user friendly for people with disabilities e.g. by reading aloud overhead projections and describing diagrams?	Y								
	Do you have the facilities such as ICT to produce written information in different formats?	Y								
	Do you ensure that staff are familiar with technology and practices developed to assist people with disabilities?	Y								

Schedule 21: Action Plan (Building and Facilities)								
_	School No:			School Name:				
Ref	Question	Recommendati ons	Time scales	Priority	Cost	Respo LEA	School	
1	Approach to School	No actions						
2	Car Parking	No actions						
3	External Ramp and Steps	VH to link with site team to mark up nosing now playground is complete		1			Completed summer 21	
4	Entrance / Reception	To look at recommendatio ns to support To book KW for accss awareness training academic year 20-21	VH and SN to book training for FS, VH, SN and KW by 1st Dec	1			Х	
5	Corridors	No actions						
6	Doors	No actions						
7	Vertical Movement6	No actions						
8	Stairs	No actions						

9	Lifts	Vh to link with HD re suitable visual and tactile information fitted at each floor level	VH to contact H and S team re tactile signage by 1.12.20 update of timescales to follow			Х
10	WCs General	No actions				
11	Accessible WCs	Vh and HD to consider LTP for Accessible toilet in KS1 area	VH to raise concern over email with HTs outlining info for future refurbishment consideration s	Care suites available. Accessible toilet included in KS1 Toilet refurb Summer 2021.		Completed
12	Changing and Shower facilities					
13	Bathrooms	No actions				
14	Fixtures and Fittings	VH to investigate the recommendatio ns and requirements for a text phone	Ask H and S re need for this update by 1.12.20			X

15		VH to raise with HD so all staff aware of the accessibility of new kitchen	new layout would make it difficult to navigate new fitting VH / SN contact catering for their equality		Х
17	Means of Escape	VH to email all teaching	7.12.20 audit of PEEPs to take place		updated copies from SENCO in Fire
18	Building Management	No actions			

			22: Actio	n Plan B - Curriculu	m		
	School No:			School Name:			
Ref	item	Recommendati ons	Time scales	Priority		Responsibility	
					Cost	LEA	School
	Curriculum	No actions					

Schedule 23: Action Plan C - Alternative formats									
	School No:			School Name:					
						Responsibility			
Ref	item	Recommendati ons	Time scales	Priority	Cost	LEA	School		
	1								